
1



Field Point Mesh [I] [C]: Pressure at 8000,000 Hz (Phase)





Fig 13



CONFIDENTIAL

Sibecaste

Field Point Mean [I]
[C]: Fressure at 8000,000 Hz (Phase)

